

Technical Reports

2010-2011

1. A report on under water abrasion test carried out on M30A20 grade concrete specimens from Kol Dam HE Project, HP.
2. A report on chemical analysis of seepage water sample collected from the inspection gallery of Tehri Dam Project, Uttarakhand
3. Report on construction materials investigations of Bowla-Nandprayag H.E. Project, Uttarakhand.
4. Technical reports on physical and chemical properties of Micro silica samples from Koteshwar H.E Project, Uttarakhand
5. Report on field and laboratory investigations to assess the in situ strength and quality of concrete in RCC columns and roof slab of a framed building of Directorate of Atomic Energy building at R.K.Puram, New Delhi.
6. A comprehensive report on water quality analysis carried out during three seasons of the year for Rihand H.E project, UP
7. A report on under water abrasion test on cylindrical concrete samples from Baglihar H.E. Project, J&K.
8. Report on compressive strength of mass concrete cores of size of 150 mm x 150 mm height extracted from dam blocks of KHEP, Uttarakhand.
9. Report on determination of mica content in the samples collected from the potential sand borrow areas of Renukaji H.E project, H.P.
10. Report on laboratory investigation of rock for the location of Surge shaft & Power House of Tawang HE Project, Stage-I, Arunachal Pradesh
11. Report on laboratory investigation of rock for the location of Surge shaft of Tawang HE Project, Stage-II, Arunachal Pradesh
12. Report on hydraulic fracturing test in power house drift of Shong Tong HE Project, HP.
13. Report on seismic refraction Survey for Shongtong Karcham Project HP
14. A detailed report on field and laboratory testing of construction materials collected during the 10th visit made by CSMRS team for inspection of QC works at Koteshwar under MoU of Koteshwar H.E. Project, Uttarakhand
15. A report on chemical analysis of PSC and OPC samples from Koteshwar H.E. Project, Uttarakhand.
16. Report on the structural Assessment of Mass Concrete Strength Examination of Tilaiya Dam, Koderma (Jharkhand).
17. 17. A detailed report on field and laboratory testing of construction materials collected during the 12th visit made by CSMRS team for inspection of QC works at Koteshwar under MoU for Koteshwar H.E. Project, Uttarakhand.
18. Report on seismic refraction survey for Machherwa Project, M.P.
19. Report on deformability characteristics of rock mass in the power house drift of Sainj HE Project, H.P
20. Report on Water samples from Koteshwar Project

21. Report on Underwater scanning of intake structure of Tehri Dam
22. Report on soil investigation Mandoli Borrow areas for Renukaji Dam Project, H.P.
23. Report on laboratory investigation of rock from HRT location of Shongtong-Karchham H.E. Project, H.P.
24. Report on laboratory investigation of rock from Powerhouse location of Shongtong-Karchham H.E. Project, H.P.
25. Report on non destructive testing using PUNDIT for Pandoh Dam, Himachal Pradesh
26. Report on insitu quality of concrete in hall No. 7 Pragati Maidan, New Delhi
27. Report on instrumentation of underground power house for Sardar Sarovar Project, Gujarat.
28. Report on Laboratory Testing of Geotextiles and GI wires from Farakka Barrage project, West Bengal
29. Report on Soil Investigation on the Foundation Soil Samples of Kabrai Dam Project, Mahoba, Uttar Pradesh
30. Report on soil investigations of borrow area samples for Kabrai Dam Project, Mahoba, Uttar Pradesh
31. Report on laboratory investigations of soil samples from Salma borrow area – II of Salma dam project, Afghanistan
32. Report on foundation soil samples from extended portion of Dam Kabrai Dam Project, Mahoba, Uttar Pradesh
33. Report on Laboratory Investigations on Fly Ash and Sand Samples Collected for Ash Dyke for Bongaigaon Thermal Power Plant (NTPC Ltd.), Salakati, Kokrajhar, Assam
34. Report on Laboratory Investigations on Fill Materials Collected from Borrow Areas for the proposed ash dykes for Bongaigaon Thermal Power Plant (NTPC Ltd.), Salakati, Kokrajhar, Assam
35. Report on Laboratory Testing on Nonwoven Geotextile for Bata river project, Himachal Pradesh
36. Report on soil investigations of Mandoli borrow area samples for Renukaji Dam project, Himachal Pradesh
37. Report on soil investigations of 'C' borrow area samples for Renukaji Dam project, Himachal Pradesh
38. Report on soil investigations of 'D' borrow area samples for Renukaji Dam project, Himachal Pradesh
39. Report on soil investigations of Oan Khadri borrow area samples for Renukaji Dam project, Himachal Pradesh
40. Report on soil investigations from two borrow areas for impervious core of coffer dams for Punatsangchu – I Hydroelectric project, Bhutan
41. Report on soil investigations of dam body samples for Kabrai Dam Project, Mahoba, Uttar Pradesh
42. Report on XRD analysis for leachate material from Tehri Dam Project, Uttarakhand.
43. Report on construction materials, admixtures, water and cement samples from Koteswar H.E. Project, Uttarakhand
44. Report on laboratory investigation of rock from surge shaft area for Shongtong-Karchham H.E. Project, H.P.

45. Report on field investigation of rock using Goodman Jack Tests of Rangit HE Project, Sikkim
46. Report on laboratory investigation of rock of Bogudiyar Sirkari H.E. project, Uttarakhand
47. Report on laboratory investigation of rock of Salma Dam Project, Afghanistan
48. Report on hydro fracturing test for Sainj H.E. project, Himachal Pradesh
49. Report on soil investigation of `B` borrow area samples from Renukaji Dam Project, Himachal Pradesh
50. Report on construction materials investigations for Bogudiyar Sirkari H.E. Project, Uttarakhand
51. Report on construction materials investigation for Mapang Sirkari H.E. project, Uttarakhand
52. Report on construction materials investigations for Ranjit H.E. Project, Stage-IV, Sikkim
53. Report on construction materials and cement samples from Salma Dam Project, Afghanistan
54. Report on under water abarasion test carried out on M30A20 grade concrete specimens with micro silica from Kol Dam H.E. project, HP
55. A detailed report on field and laboratory testing of construction materials collected during the 13th visit made by CSMRS team for inspection of QC works at Koteswar under MoU for Koteswar H.E. Project, Uttarakhand
56. Report on Seismic Refraction Survey of proposed Barrage site for Ujh Multipurpose Project, Kathua, J&K
57. Report on Seismic Refraction survey of proposed dam site for Ujh Multipurpose Project, J&K
58. Report on Deformability characteristics of rock mass in the power house drift of Sainj H.E. Project, Himachal Pradesh